Non Domestic Gas Safety Record

Cert. No. 232

Clima Heating Services Ltd

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure No detailed internal inspection of flues (integrity, construction and lining) has been carried out.

Company / Installer

Engineer	[redacted]
Company	Clima Heating Services Ltd
Address	14
	Flockton Crescent
	Sheffield
	South Yorkshire
Post Code	S13 9QR
Tel No.	[redacted]
Gas Safe Reg	[redacted]
ID Card No.	[redacted]

Job Address

Name	UoS Accommodation Village
Address	Derwent
	Endcliffe Avenue
	Sheffield
	South Yorkshire
Post Code	S10 3EA
Tel. No	

Customer / LandLord

Name	[redacted]
Company	Engie
Address	14
	Endcliffe Avenue
	Sheffield
	South Yorkshire
Post Code	S10 3EA
Tel. No	01142 224948

Appliance Details / Inspection Details

	Location	Appliance Type	Make	Model	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion Reading			Low Combustion Reading			Safety device(s) correct operation	Ventilation Provision satisfactory	Visual condition of flue and termination satisfactory	Flue Performance test	Appliance Serviced	Appliance safe to use
										Ratio	CO ppm	CO2 %	Ratio	CO ppm	CO2 %						
1	Boiler Room	Central Heating Boiler	Viessmann	Vitodens 300 WB3A - 66kW	FF	NA	Visual	NA	NA		NA	NA		NA	NA	NA	NA	NA	NA	NA	NA
2	Boiler Room	Central Heating Boiler	Viessmann	Vitodens 300 WB3A - 66kW	FF	NA	Visual	NA	NA		NA	NA		NA	NA	NA	NA	NA	NA	NA	NA
3	Boiler Room	Central Heating Boiler	Viessmann	Vitodens 300 WB3A - 66kW	FF	NA	Visual	NA	NA		NA	NA		NA	NA	NA	NA	NA	NA	NA	NA
4	Boiler Room	Central Heating Boiler	Viessmann	Vitodens 300 WB3A - 66kW	FF	NA	Visual	NA	NA		NA	NA		NA	NA	NA	NA	NA	NA	NA	NA
5	Boiler Room	Central Heating Boiler	Viessmann	Vitodens 300 WB3A - 66kW	FF	Yes	Yes	NA	66.1	0.0001	20	9.2	0.0001	11	9.0	Yes	Yes	Yes	Pass	NA	Yes
6	Boiler Room	Central Heating Boiler	Viessmann	Vitodens 300 WB3A - 66kW	FF	NA	Visual	NA	NA		NA	NA		NA	NA	NA	NA	NA	NA	NA	NA

Defects / Identified

		Labels and Warning Notice Issued
1		No
2		No
3		No
4		No
5		No
6		No

Emergency Control Accessible NA

Gas Tightness Satisfactory NA

Gas Installation Pipework Visual Inspection Satisfactory NA

Equipotential Bonding NA

NEXT INSPECTION DUE ON OR BEFORE 02-Mar-2023

Comments

GSIUR 26.9 checks on Boiler 5 following replacement of faulty Ignition Electrode

Signatures

Issued by:	Signed	[redacted]	Received by: Signed		Date 02-Mar-2022
Print Name			Print Name	[redacted]	